


**Varžtas cilindrine galvele,
vidiniu šešiakampiu**

**pagal ISO 4762
acc. to ISO 4762**

DIN 912

PN 82302

Hexagon socket head cap screws



Matmenys

Dimensions

d	M3	M4	M5	M6	M8	M10	M12	(M14)	M16	(M18)	M20	(M22)*
P	0,5	0,7	0,8	1	1,25	1,5	1,75	2	2	2,5	2,5	2,5
b _{min}	18	20	22	24	28	32	36	40	44	48	52	56
dk	max ¹⁾	5,5	7	8,5	10	13	16	18	21	24	27	30
	max ²⁾	5,68	7,22	8,72	10,22	13,27	16,27	18,27	21,33	24,33	27,33	30,33
	min	5,32	6,78	8,28	9,78	12,73	15,73	17,73	20,67	23,67	26,67	29,67
k	3	4	5	6	8	10	12	14	16	18	20	22
s _{nom}	2,5	3	4	5	6	8	10	12	14	14	17	17

d	M24	(M27)*	M30	(M33)*	M36	M42	M48	M56
P	3	3	3,5	3,5	4	4,5	5	5,5
b	60	66	72	78	84	96	108	124
dk	max ¹⁾	36	40	45	50	54	63	72
	max ²⁾	36,39	40,39	45,39	50,39	54,46	63,46	72,46
	min	35,61	39,61	44,61	49,61	53,54	62,54	71,54
k	24	27	30	33	36	42	48	56
s _{nom}	19	19	22	24	27	32	36	41

1) varžtams lygia galvele

2) varžtams su grioveliu po galvele

() – nerekomenduojami matmenys

*- matmenys pagal seną DIN standartą

P – sriegio žingsnis

1) for plain heads

2) for knurled heads

() – not recommended dimensions

*- dimensions acc. to old DIN standard

P – thread pitch